

### Part-I

#### Performa For The Safety of School Building

(To be filled by the Head of School/Institute)

1. Name of the School ..... D.G.S.G. PUBLIC SCHOOL ✓
2. Location ..... 1464, ST. No-11, GILL CANAL, SHIMLA PURI, LDH-3 ✓
3. Plot Area ..... 44526 Sft. = 4946 Sq. Yard
4. Plint Area ..... 7683 Sft. G.F. (NEW BUILD) ✓
5. Number of Storey ..... (BASEMENT, G.F., F.F., S.F.)
6. Year of Construction of building ..... 2003-04 ✓
7. Supervision of the qualified Engineer,  
the following details may be given :
  - a) Name of the Engineer ..... BALBIR SINGH ✓
  - b) Address ..... # 1988, MAHARAJ NAGAR, LDH.
  - c) Set of structure Drwaing used in the  
Construction if available ..... NO
  - d) Name of The Architect ..... NO ✓
8. Whether the building has been constructed for the purpose of
  - a) School (Yes/No) ..... YES
  - b) Resentional purpose and converted  
for use as a school (Yes/No) ..... NO
9. Materials used for Roof :
  - a) R.C.C slabs (Yes/No) ..... YES
  - b) R.S joists and Battens (Yes/No) ..... NO
  - c) Wooden joists and Battens (Yes/No) ..... NO
10. Materials used for Walls :
  - a) Mud Mortar (Yes/No) ..... NO
  - b) Cement Mortar (Yes/No) ..... YES
  - c) Plaster (i) Lime Mortar (Yes/No) .....  
(ii) Cement Mortar (Yes/No) ..... YES
11. Flooring :
  - a) Conglomerate (Yes/No) ..... NO
  - b) Terrazzo (Yes/No) ..... YES
  - c) Brick Paving (Yes/No) ..... NO
12. Detailed Drawing indicating dimensions  
of the rooms along with size and location  
of doors and windows.

ATTACHED

  
Principal  
D.G.S.G. PUBLIC SCHOOL  
Gill Canal, Shimlapuri, Ludhiana-3.

No. D/2020-21/15

**Part-II**

Dt. 11.6.2020

I have visited the above mentioned school on 10/6/2020..... and have visually inspected it from all angles of safety and I found it fit for normal use a School building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of works from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or leaves of roof etc. Immediately Inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use upto 31/3/2021.....  
(indicate year upto which it can be used)



Sub Divisional Engineer,  
Provincial Sub Division No. 3,  
P.W.D. B&R, Br. LUDHIANA.

