

**Part-I**

**Performa For The Safety of School Building**  
(To be filled by the Head of School/Institute)

1. Name of the School ..... D.G.S.G. PUBLIC SCHOOL .....
2. Location ..... 1464, S.T. No:-11, GILL CANAL, SHIMLA PURI, LDH-3 .....
3. Plot Area ..... 44520 S.F.T. = 4946.66 SQ. YARD .....
4. Plint Area ..... 7683 S.S.F.T. G.F. (NEW BUILD) .....
5. Number of Storey ..... BASEMENT, G.F., F.F., S.F., .....
6. Year of Construction of building ..... 2003-04 .....
7. Supervision of the qualified Engineer,  
the following details may be given :
  - a) Name of the Engineer ..... MALIK ENGINEERS AND ARCHITECTS .....
  - b) Address ..... UPKAR NAGAR, CIVIL LINES, LDH: .....
  - c) Set of structure Drwaing used in the ..... No .....
  - Construction if available .....
  - d) Name of The Architect ..... No .....
8. Whether the building has been constructed for the purpose of
  - a) School (Yes/No) ..... YES .....
  - b) Resentional purpose and converted  
for use as a school (Yes/No) ..... No .....
9. Materials used for Roof :
  - a) R.C.C slabs (Yes/No) ..... YES .....
  - b) R.S joists and Battens (Yes/No) ..... NO .....
  - c) Wooden joists and Battens (Yes/No) ..... NO .....
10. Materials used for Walls :
  - a) Mud Mortar (Yes/No) ..... NO .....
  - b) Cement Mortar (Yes/No) ..... YES .....
  - c) Plaster (i) Lime Mortar (Yes/No) .....
  - (ii) Cement Mortar (Yes/No) ..... YES .....
11. Flooring :
  - a) Conglomerate (Yes/No) ..... NO .....
  - b) Terrazzo (Yes/No) ..... YES .....
  - c) Brick Paving (Yes/No) ..... NO .....
12. Detailed Drawing indicating dimensions  
of the rooms along with size and location  
of doors and windows.

ATTACHED

*English*

Principal  
DGSG Public School  
Shimla Puri, LUDHIANA



D/2023-24 / 28

CA 2/5/2023.  
**Part-II**

I have visited the above mentioned school on 28/4/2023..... and have visually inspected it from all angles of safety and I found it fit for normal use a School building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of works from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or leaves of roof etc. Immediately Inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use upto 31/3/2024.....  
(indicate year upto which it can be used)

*Amrinder*  
Sub Divisional Engineer,  
Provincial Sub Division No. 8,  
P.W.D. B&R, Br. LUDHIANA.

28/4/2023

ATTACHED  
DGS Public School  
Ludhiana