Part-I
Performa For The Safety of School Building
(To be filled by the Head of School/Institute)

1.	Name of the School	DGSG PUBLIC SCHOOL
2.	Location	1464, ST. NO-11, GILL CANAL, SHIMLD PURI, LDHOS
3.	Plot Area	44520 S.FT - 4946.66 SQ YARD
4.	Plint Area	.7.683.5. S.FT. G.F. (MEW BUILD)
	Number of Storey	BASEMENT, G.F. F.F. S.F.
6.	Year of Construction of building	200364
7.	Supervision of the qualified Enginee	т,
	the following details may be given:	
	a) Name of the Engineer	MALIK ENGINEERS AND ARCHITECTS
	b) Address	. UPKAR NAGAR, CIVIL LINES, LOH:
	c) Set of structure Drwaing used in	theNo
	Construction if available	
	d) Name of The Architect	No.
8.	Whether the building has been const	ructed for the purpose of
	a) School	(Yes/No)
	b) Residentional purpose and conver	rted
	for use as a school	(Yes/No)
9.	Materials used for Roof:	
	a) R.C.C slabs	(Yes/No) YES
-	b) R.S joists and Battens	(Yes/No) No
	c) Wooden joists and Battens	(Yes/No)No
10.Materials used for Walls:		
	a) Mud Mortar	(Yes/No)
	b) Cement Mortar	(Yes/No)YES
	c) Plaster (i) Lime Mortar	(Yes/No)
	(ii) Cement Mortar	(Yes/No)YES.
	Flooring:	
	a) Conglomerate	(Yes/No)
	b) Terrazzo	(Yes/No)
	c) Brick Paving	(Yes/No)
12. Detailed Drawing indicating dimensions		
	of the rooms along with size and loc	ation ATTACHED
	of doors and windows.	

DGSG Public School Shimla Puri, LUDHIANA

2023-24/28 Ct 3/5/2023.
Part-II

In case any addition / alteration of expansion and moditreation of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of works from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or leaves of roof etc. Immediately Inspection of the undersigned be arranged to check the stability and safety of the building.

Rub DiMelonal Engineer, Provincial Sub Division No. 8, W.D. Bar, Br. LUDHIANA,