


PART- 1

Performa For The Safety of School Building
(To be filled by the Head of School/ institute)

1. Name of the School DGSG PUBLIC SCHOOL
2. Location 1464, ST. No. 11, GILL CANAL, SHIMLA PURI, LDH-3.
3. Plot Area 44520 S.FT. - 4946.66 SQ. YARD
4. Plinth Area 43941.5 SQ. FT.
5. Number of Storey BASEMENT, G.F., F.F., S.F. (4)
6. Year of Construction of Building 2003-04
7. **Supervision of the qualified Engineer, the following details may be given**
 - a) Name of the Engineer with qualification MALIK ENGINEERS AND ARCHITECTS
 - b) Address of Engineer UPKAR NAGAR, CIVIL LINES, LDH.
 - c) Set of Structural drawings used in the construction, if available YES
 - d) Name of Architect GABINDA MALIK
8. **Whether the building has been constructed for the purpose:**
 - a) School (Yes/ No) YES
 - b) Residential Purpose and converted for use as a School (Yes/ No) NO
9. **Materials used for Roofs:**
 - a) R.C.C. Slabs (Yes/ No) YES
 - b) R.S. joist & Battons (Yes/ No) No
 - c) Wooden joists & Battons (Yes/ No) No
10. **Materials used for walls:**
 - a) Mud Mortar (Yes/ No) No
 - b) Cement Mortar (Yes/ No) YES
 - c) Plaster (i) Lime Mortar (Yes/ No) No
 - (ii) Cement Mortar (Yes/ No) YES
11. **Flooring:**
 - a) Conglomerate (Yes/ No) No
 - b) Terrazzo (Yes/ No) YES
 - c) Brick Paving (Yes/ No) No
12. **A detailed drawing indicating dimensions of the rooms along with size and location of doors and windows.**

ATTACHED


Principal
DGSG Public School
Shimla Puri, LUDHIANA

PART-II

I have visited the above mentioned school on dated 21/6/24 and have visually inspected it from all angles of safety and find it fit for normal use as School buildings.

In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a technically specified Engineer and this certificate may be obtained after the completion of works from the undersigned.

In case the building is affected by flood or if there is settlement of walls/ foundations or leaves roofs etc. Immediate Inspection of the undersigned by arranged to check the stability and safety of the building.

This building can be safety occupied for normal use upto ... 31/3/25
(indicate upto which it can be used).

Subhvir Singh
Sub Divisional Engineer
Provincial Division No. 3,
P. W. D. & R Br., Ludhiana.

Principal
DGS Public School
Srinagar, LUDHIANA



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

Phone/Fax No. 0161-2420082

Email-ID :- eepdldnpwdpb@gmail.com

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ
ਡੀਜੀਐਸਜੀ ਪਬਲਿਕ ਸਕੂਲ,
ਸਿਮਲਾਪੁਰੀ, ਲੁਧਿਆਣਾ।

ਨੰ. 1693

ਮਿਤੀ: 26/07/2024

ਵਿਸ਼ਾ:- Regarding issue of Building Safety Certificate.

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰ.-554/2024 ਮਿਤੀ 4/06/2024

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਤੇ ਹਵਾਲੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਡੀਜੀਐਸਜੀ ਪਬਲਿਕ ਸਕੂਲ ਸਿਮਲਾਪੁਰੀ, ਲੁਧਿਆਣਾ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ ਮੁਤਾਬਕ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਮਿਤੀ 31/03/2025 ਤੱਕ ਸਹੀ ਜਾਪਦੀ ਹੈ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਵਿੱਚ ਇਸ ਦਫਤਰ ਦੀ ਮੰਨਜੂਰੀ ਤੋਂ ਬਗੈਰ ਕੋਈ ਵੀ ਐਡੀਸ਼ਨਲ ਅਲਟਰੇਸ਼ਨ ਨਾ ਕੀਤੀ ਜਾਵੇ। ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦੀ ਵੈਧਿਤਾ 05/03/2025 ਤੱਕ ਹੈ ਅਤੇ 05/03/2025 ਤੋਂ ਬਾਅਦ ਨਵਾਂ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣਾ ਯਕੀਨੀ ਬਣਾਇਆ ਜਾਵੇ।

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ. ਨਿ. ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰ. 194 ਮਿਤੀ 24/06/2024 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਅਤੇ ਅਗਲੀ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

— ਸਹੀ —
ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ. ਨਿ. ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।