

Part - 1

**Performa For The Safety School Building**  
(To be filled by the Head of School / Institute)

1. Name of School DGSG PUBLIC SCHOOL
2. Location 1464, ST. NO. 11, GILL CANAL, SHIMLAPURI, LDH
3. Plot Area 44520 SQ. FT. .... 4946.66 SQ. YARD
4. Plinth Area 44456.5 SQ. FT. ....
5. Number of Storey BASEMENT, GF, FF, SF (4)
6. Year of Construction of building 2003-04
7. Supervision of the qualified Engineer,  
The following details may be given:
  - a) Name of the Engineer MALIK ENGINEERS AND ARCHITECTS
  - b) Address UPKAR NAGAR, CIVIL LINES, LDH
  - c) Set of Structure Drawing used in the construction if available YES
  - d) Name of the Architect GOBINDA MALIK
8. Whether the building has been constructed for the purpose of :
  - a) School ( Yes / No ) YES
  - b) Residential purpose and converted for use as a school ( Yes / No ) NO
9. Materials used for Roof:
  - a) R.C.C. slabs ( Yes / No ) YES
  - b) R.S. Joists and Battens ( Yes / No ) NO
  - c) Wooden Joists and Battens ( Yes / No ) NO
10. Materials used for walls:
  - a) Mud Mortar ( Yes / No ) NO
  - b) Cement Mortar ( Yes / No ) YES
  - c) Plaster (i) Lime Mortar ( Yes / No ) NO  
(ii) Cement Mortar ( Yes / No ) YES
11. Flooring :
  - a) Conglomerate ( Yes / No ) NO
  - b) Terrazzo ( Yes / No ) YES
  - c) Brick Paving ( Yes / No ) NO
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows

ATTACHED

*Jugish*  
Principal  
Signature with stamp of  
DGSG Public School  
The Head of the School / Institute  
Shimla Puri, LUDHIANA

**Part-II**  
**(To be filled by S.D.E. of P.W.D. B&R Department)**

I have visited the above mentioned school on 06/06/2025 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The Area as written in the application form has been verified and found correct as per site.

The fee submitted is correct as per built up area of School and Govt. notification for fees.

The fee deposited by the School has been verified on portal.

This building can be safely occupied for normal use up to 31/03/2026 (indicate year up to which it can be used).

  
**Sub Divisional Engineer**

**Sub Divisional Engineer,  
Provincial Sub Division No. 3,  
P.W.D. B&R, Br. LUDHIANA.**

