



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

Phone/Fax No. 0161-2420082

Email-ID :- eepdldnpwdpb@gmail.com

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ
ਡੀ.ਜੀ.ਐਸ.ਜੀ ਪਬਲਿਕ ਸਕੂਲ,
ਸਿਮਲਾਪੁਰੀ, ਲੁਧਿਆਣਾ।

ਨੰ. 898

ਮਿਤੀ: 05/06/2026

ਵਿਸ਼ਾ:- Regarding issue of Building Safety Certificate.

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰ.DGSGPS/659/26 ਮਿਤੀ 10/04/2026

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਤੇ ਹਵਾਲੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਡੀ.ਜੀ.ਐਸ.ਜੀ ਪਬਲਿਕ ਸਕੂਲ ਸਿਮਲਾਪੁਰੀ, ਲੁਧਿਆਣਾ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ ਮੁਤਾਬਕ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਮਿਤੀ 31/03/2027 ਤੱਕ ਸਹੀ ਜਾਪਦੀ ਹੈ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਵਿੱਚ ਇਸ ਦਫਤਰ ਦੀ ਮੰਨਜ਼ੂਰੀ ਤੋਂ ਬਗ਼ੈਰ ਕੋਈ ਵੀ ਐਡੀਸ਼ਨਲ ਅਲਟਰੇਸ਼ਨ ਨਾ ਕੀਤੀ ਜਾਵੇ।

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 3, ਲੁਧਿਆਣਾ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰ. 170 ਮਿਤੀ 01/06/2026 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਅਤੇ ਅਗਲੀ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਸ਼ਾਹੀ
ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ.,
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।

Part - 1

Performa For The Safety School Building
(To be filled by the Head of School / Institute)

1. Name of School **DGSG PUBLIC SCHOOL**
2. Location **1464, ST. NO. 11, GILL CANAL, SHIMLA PURI, LDH.**
3. Plot Area **44520 SQ. FT., 4946.66 SQ. YARD**
4. Plinth Area **44456.5 SQ. FT.**
5. Number of Storey **BASEMENT, GF, FF, SF (4)**
6. Year of Construction of building **2003-04**
7. Supervision of the qualified Engineer,
The following details may be given:
 - a) Name of the Engineer **MALIK ENGINEERS AND ARCHITECTS**
 - b) Address **UPKAR NAGAR, CIVIL LINES, LDH**
 - c) Set of Structure Drawing used in the construction if available **YES**
 - d) Name of the Architect **GOBINDA MALIK**
8. Whether the building has been constructed for the purpose of :
 - a) School **(Yes/No) YES**
 - b) Residential purpose and converted for use as a school **(Yes/No) NO**
9. Materials used for Roof:
 - a) R.C.C. slabs **(Yes/No) YES**
 - b) R.S. Joists and Battens **(Yes/No) NO**
 - c) Wooden Joists and Battens **(Yes/No) NO**
10. Materials used for walls:
 - a) Mud Mortar **(Yes/No) NO**
 - b) Cement Mortar **(Yes/No) YES**
 - c) Plaster
 - (i) Lime Mortar **(Yes/No) NO**
 - (ii) Cement Mortar **(Yes/No) YES**
11. Flooring :
 - a) Conglomerate **(Yes/No) NO**
 - b) Terrazzo **(Yes/No) YES**
 - c) Brick Paving **(Yes/No) NO**
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows **ATTACHED**

Signature with stamp of
The Head of the School / Institute

(Signature)
Principal
DGSG Public School
Shimla Puri, LUDHIANA

Part-II
(To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 19/05/2026 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The Area as written in the application form has been verified and found correct as per site.

The fee submitted is correct as per built up area of School and Govt. notification for fees.

The fee deposited by the School has been verified on portal.

This building can be safely occupied for normal use up to 31/03/2027 (indicate year up to which it can be used).


Sub Divisional Engineer

Sub Divisional Engineer,
Provincial Sub Division No. 3,
P.W.D. B&R, Br. LUDHIANA.

